## 9/AF 4266

	4 -		F	7
DIST		_	ļu	4
BRE ZKE JC	:		1	7
BUPLINGAME COPP RD	AF	1	1	7
COPP RD				7
CPOUCHER (	W C			7
DAVIS J.G				7
EVERED JE			χ	T
FERRERA DV	٧		_	$\mathcal{I}$
FERRIS L R		4	_	1
FRAIKOR, FJ		4	_	4
FRANCIS, G E GOODWIN, R		4		1
HEALY, TJ		4	_	+
DEKER E.H.		+		+
JENS, J P		+	-	t
KEELE, P B		+		t
KERSH, JM		$\dagger$	$\overline{\mathbf{v}}$	t
KIRBY WA		+	Δ.	H
KIRKEBO, JA		+	_	┝
LEE, E M		1	_	r
MAJESTIC J.R.		T		Г
MATHEWS, TA		Ι		
MEURRENS, B MORGAN, R V	<u>E</u>	1		
		7	2	
NORTH P		1		
PALMER LA POTTER, GL		L	_	_
POTTER, G L PIZZUTO, V M		4	4	_
BHOADES JI		۲	7	_
SAFFELL R.F.		×	7	_
SWANSON, E.R.		+-	+	_
WIEBE, JS		┢	+	-
WILKINSON, R.E	~	┢	+	_
WILLIAMS A E	<u> </u>	1	+	_
WILSON J M		1	+	_
YOUNG ER			†	-
ZANE J O			1	~
77			T	_
M.B. Arnd	T	X	Ι	_
A-y- Busp	У.,	<u>X</u>	L	_
W. F. Ewan	==	ş	+	_
B. G. Pont	шa	×	╀	_
D M Smit	-	÷	┝	_
RD Linde	-	÷	H	-
J.R. Dick	7	÷	H	-
L. A. Dunst	AN	$\overline{\mathbf{v}}$	۳	-
E.D. Habbs	_7	V	-	_
,	T			-
		7	_	_
			_	-
CORRES CONTRO	$\mathcal{K}$	<b>₹</b>	x	-
TRAFFIC	$\perp$	J	_	_

CLASSIFICATION

		1
UCNI		
UNCLASSIFIED	$\overline{\mathbf{z}}$	-
CONFIDENTIAL		_
SECRET		

AUTHORIZED CLASSIFIER
/SIGNATURE

AGALINIA
DATE

IN REPLY TO LTR NO

PC# LTR APPROVALS ROL ROL MM ORIG & TYPIST INITIALS

### EG&G ROCKY FLATS

EG&G ROCKY FLATS, INC ROCKY FLATS PLANT, P O BOX 464, GOLDEN, COLORADO 80402-0464 • (303) 966 7000

July 17, 1991

91-RF-4266

Robert M Nelson, Jr Manager DOE, RFO



Attn John Rampe

OUT-OF-SPECIFICATION SURFACE WATER SAMPLE - JMK-0340-91

Attached please find a Water Sample Report and map for a surface water sample which was out-of-specification with respect to current standards for Plutonium-239 Listed below is a summary of the unvalidated data for this surface water station. The reporting threshold designated by the Inter-agency Agreement (IAG) and the Colorado Water Quality Control Commission (CWQCC) is also listed.

Location	Sample Date	Analyte	Result	Threshold Limit
A-3 Pond	3/12/91	Pu-239	079 pCi/l	05 pCi/l
A-3 Pond	3/12/91	Pu-239	011 pCi/l*	05 pCı/l

A-3 Pond is considered a critical station and is an NPDES monitoring point, however, A-3 Pond does not discharge offsite. The average value between the two analytical results is 0.045 pCi/l. This value is still below the threshold limit

EMAD will closely monitor this station for this particular analyte. Future monitoring should determine if additional investigation measures will be required. This surface water station is located in the Walnut Creek drainage, OU 6, and will be remediated in accordance with the Inter-Agency Agreement (IAG)

JZM Kersh, Associate General Manager Environmental & Waste Management

DOCUMENT CLASSIFICATION REVIEW WAIVER PER CLASSIFICATION OFFICE

ħ,

BAM nkg

Orig and 1 cc - R M Nelson, Jr

Attachment As Stated

1/3

# OUT OF SPECIFICATION WATER SAMPLE REPORT

Sample No NP55999WC

Date 3/12/91 Lab 123

Location. A-3 Pond

Map attached Yes

Quality Assurance Concerns. Data are not validated

<u>Parameter</u>	Threshold Limit (/I)	Result (/I)
Plutonium-239	05 pCı/l	079 pCı/l
Plutonium-239	05 pCi/l	011 pCi/l *

<sup>\*</sup>Sample reanalysis result

Source of Threshold Limit IAG, CWQCC

Reporting Required? Yes Nature of Requirement. Critical Station

#### Location of nearest surface water.

Walnut Creek Water Classification Segment 5

#### Source of observed results (if known):

None of the upstream surface water stations exhibit any Plutonium contamination

#### Current control/investigative actions

Reanalysis of this sample has been requested to determine the validity of the analytical result


#### Proposed control/investigative actions

Further characterization of this area will be included as part of Operable Unit 6, Walnut Creek

#### Other comments.

Radionuclides are not required NPDES discharge permit parameters

Date of Report, June 20, 1991 Preparer. M L Sievers & B A Montano



DISCHARGE POINTS - ROCKY FLATS PLANT